

Tingey, Christopher

From: Tingey, Christopher
Sent: Friday, June 17, 2016 11:21 AM
To: Rosalind Karlin
Cc: Hurlbut, Bill; Leigh Kuykendall
Subject: RE: NBU #16-6 AOR Wells

Thanks Rosalind,

Please send the work completed form for the plugging of 15-W24 when it is done. The plugging records for 16-5 and 16-8 don't indicate a problem that needs to be corrected. They are plugged similar to other wells in the field from that period that we have deemed adequate. Plus, the monitoring well system is in place because of concerns about old wells. 16-W22 is adequate as a shut-in injector with future plans for P&A.

Christopher Tingey
Environmental Scientist
U.S. EPA, Region 6 (6WQ-SG)
1445 Ross Avenue
Dallas, TX 75202
214-665-8364

From: Rosalind Karlin [mailto:rosalind.karlin@chaparralenergy.com]
Sent: Friday, June 17, 2016 10:37 AM
To: Tingey, Christopher <tingey.christopher@epa.gov>
Cc: Hurlbut, Bill <Hurlbut.William@epa.gov>; Leigh Kuykendall <leighk@chaparralenergy.com>
Subject: NBU #16-6 AOR Wells

Chris,

Just following up with you regarding your questions.

NBU #16-22: The decision was made to plug this well after earlier attempts to correct injection zone failed.

NBU #15-24: Plugging (top plug) will be completed soon.

NBU #16-5 & NBU #16-8: These wells are similar to the previously plugged old wells in the AORs. I've attached the records for this wells for your review, but are as shown in the tabulations.

Let me know if you need anything else.

Thanks!

Rosalind Karlin

Regulatory Compliance Specialist - EOR
O: 405.426.6690 / F: 405.425.3790
Rosalind.Karlin@chaparralenergy.com

Tingey, Christopher

From: Rosalind Karlin <rosalind.karlin@chaparralenergy.com>
Sent: Friday, June 17, 2016 10:37 AM
To: Tingey, Christopher
Cc: Hurlbut, Bill; Leigh Kuykendall
Subject: NBU #16-6 AOR Wells
Attachments: 5.PDF; 8.PDF

Chris,

Just following up with you regarding your questions.

NBU #16-22: The decision was made to plug this well after earlier attempts to correct injection zone failed.

NBU #15-24: Plugging (top plug) will be completed soon.

NBU #16-5 & NBU #16-8: These wells are similar to the previously plugged old wells in the AORs. I've attached the records for this wells for your review, but are as shown in the tabulations.

Let me know if you need anything else.

Thanks!

Rosalind Karlin
Regulatory Compliance Specialist - EOR
O: 405.426.6690 / F: 405.425.3790
Rosalind.Karlin@chaparralenergy.com